




~DIN 7504 N

Standard withdrawn

ecosyn®-MRX



**BN 14727**

**Pozi pan head self-drilling screws**

form Z

Stainless steel



- ~UNI 8118



Fasteners out of martensitic stainless steel (e.g. 1.4116 / 1.4122 / 1.4034): susceptible to stress corrosion cracking under certain environmental conditions! Further notice to residual risks can be found in the introduction section (I).



A technical brochure is available on request

Article#	d <sub>1</sub>	d <sub>2</sub> max.	k max.		m~		L
1477218	ST3,5	6,9	2,6	2	3,9	1,3-2,25	9,5
1477226							13
1477242							16
3484314							19
3484315							22
3484316							25
1477250	(ST3,9)	7,5	2,8	2	4,1	1,3-2,4	13
1477269							16
1477277							19
3484317							22
1478664							25
3484318							32
3484321	ST4,2	8,2	3,05	2	4,3	1,75-3	13
1478672							16
1478680							19
1478699							25
1478702							32
3484322							38
1478710	ST4,8	9,5	3,55	2	4,7	1,75-4,4	13
1478729							16
1478737							19
1478745							25
1478761							32
3484324							38
3484325							45
1478788							50
3484326							60